

CERTIFICATE OF COMPLIANCE

Certificate Number E359349
Report Reference E359349-20210426
Date 2022-January-14

Issued to: Suzhou Talesun Solar Technologies Co Ltd
1 TALESUN RD CHANGKUN INDUSTRIAL PARK
SHAJIABANG TOWN
CHANGSHU JIANGSU 215542 CN

This is to certify that representative samples of PHOTOVOLTAIC MODULES AND PANELS WITH SYSTEM VOLTAGE RATINGS OVER 600 VOLTS
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.


Standard(s) for Safety: UL Standard for Safety for Photovoltaic (PV) Module Safety Qualification - Part 1: Requirements for Construction, UL 61730-1, First Edition, Part 2: Requirements for Testing, UL 61730-2, First Edition, CSA C22.2 No. 61730-1, Photovoltaic (PV), module safety qualification — Part 1: Requirements for construction, Edition 2 and CSA C22.2 No. 61730-2, Photovoltaic (PV) module safety qualification — Part 2: Requirements for testing,

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E359349
Report Reference E359349-20210426
Date 2022-January-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

USL/CNL - Models:

TP6F72M(H)-420, TP6F72M(H)-415, TP6F72M(H)-410, TP6F72M(H)-405, TP6F72M(H)-400, TP6F72M(H)-395, TP6F72M(H)-390, TP6F72M(H)-385
TP6F72M-420, TP6F72M-415, TP6F72M-410, TP6F72M-405, TP6F72M-400, TP6F72M-395, TP6F72M-390, TP6F72M-385

TP6F60M(H)-350, TP6F60M(H)-345, TP6F60M(H)-340, TP6F60M(H)-335, TP6F60M(H)-330, TP6F60M(H)-325
TP6F60M-350, TP6F60M-345, TP6F60M-340, TP6F60M-335, TP6F60M-330, TP6F60M-325

TP6L72M(H)-455, TP6L72M(H)-450, TP6L72M(H)-445, TP6L72M(H)-440, TP6L72M(H)-435, TP6L72M(H)-430, TP6L72M-455, TP6L72M-450, TP6L72M-445, TP6L72M-440, TP6L72M-435, TP6L72M-430,
TP6L60M(H)-375, TP6L60M(H)-370, TP6L60M(H)-365, TP6L60M(H)-360, TP6L60M-375, TP6L60M-370, TP6L60M-365, TP6L60M-360,

TP7F78M(H)-595, TP7F78M(H)-590, TP7F78M(H)-585, TP7F78M(H)-580, TP7F78M(H)-575, TP7F78M(H)-570, TP7F78M-595, TP7F78M-590, TP7F78M-585, TP7F78M-580, TP7F78M-575, TP7F78M-570,

TP7F72M(H)-555, TP7F72M(H)-550, TP7F72M(H)-545, TP7F72M(H)-540, TP7F72M(H)-535, TP7F72M(H)-530, TP7F72M(H)-525,
TP7F72M-555, TP7F72M-550, TP7F72M-545, TP7F72M-540, TP7F72M-535, TP7F72M-530, TP7F72M-525,

TP7F66M(H)-505, TP7F66M(H)-500, TP7F66M(H)-495, TP7F66M(H)-490, TP7F66M(H)-485, TP7F66M-505, TP7F66M-500, TP7F66M-495, TP7F66M-490, TP7F66M-485,

TP7F60M(H)-460, TP7F60M(H)-455, TP7F60M(H)-450, TP7F60M(H)-445, TP7F60M(H)-440, TP7F60M(H)-435, TP7F60M-460, TP7F60M-455, TP7F60M-450, TP7F60M-445, TP7F60M-440, TP7F60M-435


TP7F54M(H)-415, TP7F54M(H)-410, TP7F54M(H)-405, TP7F54M(H)-400, TP7F54M(H)-395, TP7F54M-415, TP7F54M-410, TP7F54M-405, TP7F54M-400, TP7F54M-395,

TP8F66M(H)-660, TP8F66M(H)-655, TP8F66M(H)-650, TP8F66M(H)-645, TP8F66M(H)-640, TP8F66M(H)-635, TP8F66M-660, TP8F66M-655, TP8F66M-650, TP8F66M-645, TP8F66M-640, TP8F66M-635,

TP8F60M(H)-600, TP8F60M(H)-595, TP8F60M(H)-590, TP8F60M(H)-585, TP8F60M(H)-580, TP8F60M(H)-575, TP8F60M-600, TP8F60M-595, TP8F60M-590, TP8F60M-585, TP8F60M-580, TP8F60M-575,

TP8F54M(H)-540, TP8F54M(H)-535, TP8F54M(H)-530, TP8F54M(H)-525, TP8F54M(H)-520, TP8F54M(H)-515,

TP8F54M-540, TP8F54M-535, TP8F54M-530, TP8F54M-525, TP8F54M-520, TP8F54M-515



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>